



AMENDMENTS TO THE SPECIFICATION

In the Specification:

Please **AMEND** the specification as shown in the following marked up paragraph, which shows changes made relative to the immediate prior version.

Page 7, lines 5-10:

The A/D converter receives analog image signals from the CCD photographing unit 120 and converts the signals to digital image data 101. Next, the digital image data 101 are output to the image size converter 200. Here, the CCD photographing unit 120, with reference to FIG. 4, measures a distance between a subject and image through various measuring methods such as laser and ultrasonic wave. The measured distance data are output to the image size converter 200.